Appendix C

CSL Data from Site #2



Figure C1 CSL Data from Site #2 Abutment 1 Shaft 1



Figure C2 CSL Data from Site #2 Abutment 1 Shaft 2



Figure C3 CSL Data from Site #2 Abutment 1 Shaft 3



Figure C4 CSL Data from Site #2 Abutment 1 Shaft 4



Figure C5 CSL Data from Site #2 Abutment 2 Shaft 1



Figure C6 CSL Data from Site #2 Abutment 2 Shaft 2



Figure C7 CSL Data from Site #2 Abutment 2 Shaft 3



Figure C8 CSL Data from Site #2 Abutment 2 Shaft 4



Figure C9 CSL Data from Site #2 Abutment 2 Shaft 4 with Offset



Figure C10 CSL Data from Site #2 Abutment 2 Shaft 4 Retest



Figure C11 CSL Data from Site #2 Abutment 2 Shaft 4 after Repair



Figure C12 CSL Data from Site #2 CenterPier Shaft 1



Figure C13 CSL Data from Site #2 Center Pier Shaft 1



Figure C14 CSL Data from Site #2 Center Pier Shaft 2



Figure C15 CSL Data from Site #2 Center Pier Shaft 2



Figure C16 CSL Data from Site #2 Center Pier Shaft 3



Figure C17 CSL Data from Site #2 Center Pier Shaft 3



Figure C18 CSL Data from Site #2 Center Pier Shaft 4



Figure C19 CSL Data from Site #2 Center Pier Shaft 4